

## PRODUCT INFORMATION NOTICE LOG

**Part Number Family:** 92-508255-XXX

**Part Description:** TKL8255 Single Skylake PICMG1.3 SHB

**Date Established:** 20.Jan.2020

**Last Updated:** 18.May.2022

**By:** Ramiz Bilal, Technical Support Eng.

Ref #	Reason for the Change	Change Description	Effected Product	Revision (From → To)	Date Effective
880	Release	Release for production	ALL	RDA03 → D03	22.Mar.2017
888	Product Enhancement	Added several voltages to the on-board monitoring in the area of CPU, PCH, and System voltages	ALL	D03 → E04	14.July.2017
3100	Documentation	Updated BOM with parts being installed but were not driving demand.	ALL	E04 → F04	24.May.2018
3148	Process Improvement	Replaced pre-programmed part with raw part to enable internal programming.	ALL	F04 → G04	08.June.2018
3496	Process Improvement	Updated footprint of ferrite bead filters to prevent solder form wicking out of the pad during production. Updated EOL parts with active equivalents.	ALL	G04 → H05	20.Mar.2019
3585	EOL Update	Removed EOL part that is no longer utilized	ALL	H05 → J05	07.May.2019
4279	Product Enhancement	Fixed DediProg/FlashCAT programming issue. Removed R239 and R240 in order to allow programming of system SPI with both tools.	ALL	J05 → K05	23.June.2020
4415	Product Enhancement	CMOS battery from Panasonic CR2032 to Maxwell CR2032	ALL	K05 → M05	15.Sep.2020
5253	Part Availability	New artwork to support a new regulator with available stock	ALL	M05 → N06	7.Feb.2022
5276	Obsolete Part	Removed audio header	ALL	N06 → P06	16.Feb.2022
5276	Obsolete Part	Removed 1/2 DVI header	92-508255-002	N06 → P06	16.Feb.2022
5276	Obsolete Part	Removed both DVI headers	92-508255-001	N06 → P06	16.Feb.2022