



1725 MacLeod Drive
 Lawrenceville, GA 30043
 770.287.3100 ☎
 info@trentonsystems.com ✉

PRODUCT INFORMATION NOTICE LOG

Part Number Family: 92-508255-XXX

Part Description: TKL8255 Single Skylake PICMG1.3 SHB

Date Established: 20.Jan.2020

Last Updated: 20.Jan.2020

By: Toni Lynn Hauck, Quality Director

Ref #	Reason for the Change	Change Description	Effected Product	Revision (From → To)	Date Effective
880	Release	Release for production	ALL	RDA03 → D03	22.Mar.2017
888	Product Enhancement	Added several voltages to the on-board monitoring in the area of CPU, PCH, and System voltages	ALL	D03 → E04	14.July.2017
3100	Documentation	Updated BOM with parts being installed but were not driving demand.	ALL	E04 → F04	24.May.2018
3148	Process Improvement	Replaced pre-programmed part with raw part to enable internal programming.	ALL	F04 → G04	08.June.2018
3496	Process Improvement	Updated footprint of ferrite bead filters to prevent solder form wicking out of the pad during production. Updated EOL parts with active equivalents.	ALL	G04 → H05	20.Mar.2019
3585	EOL Update	Remove EOL part that is no longer utilized	ALL	H05 → J05	07.May.2019